TIB's

✦TECHNOPEDIA✦

Doc. #	Description
12030	Troubleshooting Guide II (old TIB-30)
12029	Separator Return Spring; PJR (old TIB-29)
12028	Disposal Roller; Modification (old TIB-28)
12027	2700 ADF; Modification (old TIB-27)
12026	Drum PCB; Design Change (old TIB-26)
12025	Clamp Guide; Design Change (old TIB-25)
12017	Pickup Rollers; Design Change (old TIB-17)
12023	Image Scanner Reduction (old TIB-23)
12024	Drum - P Master; Modification (old TIB-24)
12019	Reference Chart For TPH Setting With H Master
12021	Resetting Micro Processor Memory (old TIB-21)
12020	3500 Manual Adjustments; Temporary (old TIB-20)
12016	Troubleshooting Aid For Original Jam (old TIB-16)
12018	257 Image Scanner; Adjustments (old TIB-18)
12014	Pressure Hook And Lever;Design Change
12013	Upper Cutter; Modification (old TIB-13)
12015	Suction Unit; Design Change (old TIB-15)
12012	Troubleshooting Aid For Cutter Assembly
12011	Write Roller; Design Change (old TIB-11)
12010	Troubleshooting Aid For T-3 (old TIB-10)
12005	Disposal Unit; Mod Kit 1&2 (old TIB-5)
12008	Pulse Motor Cement Resistor New Type
12004	Troubleshooting Guide (old TIB-4)
12007	Jump Wire Guide (old TIB-7)
12002	Bracket; Clamp Motor (old TIB-2)
12006	WP Disc Modification (old TIB-6)
12003	IT I/O PCB (old TIB-3)

✦TECHNOPEDIA HOME✦